# Oil Field Environmental Incident Summary

Incident: 20160102114309 Date/Time of Notice: 01/02/2016 11:43

Responsible Party: ENERPLUS RESOURCES USA CORPORATION

Well Operator: ENERPLUS RESOURCES USA CORPORATION

Well Name: MUSTANG 149-93-29A-32H TF

Field Name: MANDAREE Well File #: 22665

Date Incident:1/1/2016Time Incident:16:00Facility ID Number:County:DUNNTwp:149Rng:93Sec:29Qtr:

**Location Description:** 

Submitted By: Shannon Oliver Received By:

Contact Person: Josh Ruffo

US BANK TOWER 950 17TH ST STE 2200 DENVER, CO 80202

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained in Dike: Yes - On Facility Site Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine 2 Barrels

Other

**Description of Other Released Contaminant:** 

Inspected: Written Report Received: Clean Up Concluded:

Risk Evaluation:

Low risk as worker was on location and able to respond immediately to prevent further spillage.

Areal Extent:

## **Potential Environmental Impacts:**

Low environmental impact, 2 bbls spilled and remained entirely on well site.

### Action Taken or Planned:

Discussion with water hauling company to determine potential fail safe for pop-off valves.

Wastes Disposal Location: Affected soil will be hauled to an approved oil/water waste handling facility.

Agencies Involved:

### **Updates**

Date: 1/4/2016 Status: Reviewed - Assigned to Other Agency Author: Souder, Taylor

**Updated Oil Volume:** 

**Updated Salt Water Volume:** 

**Updated Other Volume:** 

**Updated Other Contaminant** 

#### Notes:

According to the report, the release remained on location. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.